



ARCHITECTURAL LEGEND	
SYMBOL	DESCRIPTION
====	EXISTING PARTITION TO REMAIN. INSTALL LOOSE FILL INSULATION AT OFFICE AND CONFERENCE ROOM LOCATIONS AS REQUIRED.
-----	EXISTING CONSTRUCTION TO BE REMOVED.
————	NEW BUILDING STANDARD TENANT INTERIOR PARTITION TO BE INSTALLED TO UNDERSIDE OF SUSPENDED CEILING.
⌢	INDICATES EXISTING DOOR, FRAME AND HARDWARE TO REMAIN. INSTALL NEW LEVER LOCKSET W/ OFFICE FUNCTION AT OFFICE LOCATIONS AS REQUIRED. PAINT/REFINISH DOOR & FRAMES.
⌢	INDICATES NEW DOOR, FRAME AND HARDWARE TO BE INSTALLED.

EXISTING CONDITIONS PLAN

SCALE 1/8" = 1'-0"

EXISTING CONDITIONS:
HERITAGE COMMERCIAL GROUP
 HERITAGE EXECUTIVE CAMPUS AT HILLTOWN
 SUITE 705
 PERKASIE, PA

RHJ ASSOCIATES, PC
 ARCHITECTS · PLANNERS · DESIGNERS

860 FIRST AVE, STE 9A
 KING OF PRUSSIA, PA 19406
 610.337.4555

3316 S. ROCKFIELD DR
 WILMINGTON, DE 19810
 302.482.2269

DATE 03/25/21
 PROJECT NO. 2021-0150

www.rhjassoc.com